

CONSTRUCTION EQUIPMENT

568333 TUCKER PAVING VOLVO ECR58D 210864 - DIESEL ENGIN



Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

Job No: 568333 TUCKER PAVING

SAMPLE IN	IFORMATION			
Sample Number	-	VCP411552	VCP364318	
Sample Date		14 Jul 2023	11 Aug 2022	
Machine Hours		1534	670	
Oil Hours		1000	500	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	ABNORMAL	
OIT CONDI	FION			
Visc @ 100°C	cSt	13.1	12.7	
Base Number (BN)	mg KOH/g	■8.3	■ 6.7	
Oxidation (PA)	%	84	57	
CONTAMIN	IATION			
C + 0/	07		□ 0 1	

CONTAMINATION					
Soot %	%	■0.1	■ 0.1		
Nitration (PA)	%	83	78		
Sulfation (PA)	%	61	61		
Glycol	%	NEG	NEG		
Fuel	%	<1.0	< 1.0		
Silicon	ppm	■ 5	9		
Sodium	ppm	4	5		
Potassium	ppm	2	2		

WEAR	METALS			
Iron	ppm	10	1 9	
Copper	ppm	■ 6	△ 58	
Lead	ppm	■ <1	< 1	
Tin	ppm	■<1	- <1	
Aluminum	ppm	■ 3	4	
Chromium	ppm	■<1	2	
Molybdenum	ppm	48	1 7	
Nickel	ppm	■<1	■0	
Titanium	ppm	0	<1	
Silver	ppm	■ 0	0	
Manganese	ppm	1	■3	
Vanadium	ppm	0	0	

ADUITIDES					
Calcium	ppm	1820	2381		
Magnesium	ppm	536	■188		
Zinc	ppm	1237	1151		
Phosphorus	ppm	■996	918		
Barium	ppm	0	2		
Boron	ppm	18	4		



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC

8418 PALM RIVER ROAD

TAMPA, FL
US 33619

Contact: JOHN FARDELLA
JFARDELLA@ALTAEQUIPFL.COM
T: (813)630-0077
F: (813)630-2233

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VOLVO0093Unique No:10601871Signed:Wes DavisReport Date:11 Aug 2023



CONSTRUCTION EQUIPMENT





GRAPHS

