



CONSTRUCTION EQUIPMENT

SPM593192 SENNEBOGEN 835ME 835.0.2845 - REAR RIGHT FINAL DRIVE



Sample No: VCP406644
Oil Type: GEAR OIL SAE 80W90
Job No: SPM593192



SAMPLE INFORMATION

Sample Number	VCP406644	VCP399519	VCP400515	VCP378909
Sample Date	04 Aug 2023	24 May 2023	22 Mar 2023	23 May 2022
Machine Hours	5542	5027	4535	2518
Oil Hours	0	0	0	0
Oil Changed	Not Chngd	Changed	Not Chngd	Not Chngd
Sample Status	NORMAL	NORMAL	ATTENTION	NORMAL

BELSON STEEL

1685 N STATE RTE 50
 BOURBONNAIS, IL
 US 60914
 Contact: M. POZAN
 mpozan@belsonsteel.com
 T: (815)932-7416
 F:



OIL CONDITION

Visc @ 40°C	cSt	143	190	189	183
-------------	-----	------------	-----	-----	-----



CONTAMINATION

Silicon	ppm	5	19	25	4
Sodium	ppm	0	<1	<1	4
Potassium	ppm	<1	0	<1	<1



WEAR METALS

Iron	ppm	40	25	27	250
Copper	ppm	10	15	8	75
Lead	ppm	0	0	0	0
Tin	ppm	<1	0	0	0
Aluminum	ppm	<1	5	1	0
Chromium	ppm	<1	0	<1	2
Molybdenum	ppm	<1	<1	2	0
Nickel	ppm	<1	0	<1	0
Titanium	ppm	2	0	<1	0
Silver	ppm	0	0	0	0
Manganese	ppm	<1	0	<1	6
Vanadium	ppm	0	0	0	0



ADDITIVES

Calcium	ppm	148	2102	2387	30
Magnesium	ppm	5	31	30	2
Zinc	ppm	72	988	1026	61
Phosphorus	ppm	470	974	1093	1166
Barium	ppm	2	0	4	347
Boron	ppm	3	12	13	4

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: BELBOU
Unique No: 10602461
Signed: Wes Davis
Report Date: 12 Aug 2023



CONSTRUCTION EQUIPMENT



GRAPHS

