

# CONSTRUCTION EQUIPMENT SPM593014 VOLVO L120H 633335 - REAR AXLE



Sample No: VCP420648

Oil Type: VOLVO WET BRAKE TRANSAXLE OIL

**Job No:** SPM593014

SAMPLE	E INFORMATION			
Sample Number		VCP420648	 	
Sample Date		27 Jul 2023	 	
Machine Hours		613	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>40.4</b>	 	
VOLVO				
CONTAN	MINATION			
Silicon	ppm	<b>11</b>	 	
Sodium	ppm	■8	 	
Potassium	ppm	<b>3</b>	 	
WEAR N	METALS			
Iron	ppm	<b>□</b> 38	 	
Copper	ppm	1	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	0	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<b>2</b>	 	
Molybdenum		<b>3</b>	 	
Nickel	ppm		 	
Titanium	ppm	<b>□</b> <1 0		
	ppm			
Silver	ppm	0	 	
Manganese	ppm	■3	 	
Vanadium	ppm	0	 	
VOLVO				
ADDITIV	VES			
Calcium	ppm	■3904	 	
Magnesium	ppm	<b>■</b> 9	 	
Zinc	ppm	<b>1630</b>	 	
Phosphorus	ppm	<b>1333</b>	 	
Barium	ppm	<b>■1</b>	 	
Boron	ppm	<b>146</b>	 	



### **OZINGA BROS INC**

19001 OLD LAGRANDE RD MOKENA, IL US 60448 Contact: ED JONGSMA

T: (708)326-4200 F:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:OZIMOKVCUnique No:10602466Signed:Wes DavisReport Date:12 Aug 2023



# **CONSTRUCTION EQUIPMENT**





#### GRAPHS

