



# CONSTRUCTION EQUIPMENT

568333 TUCKER VOLVO ECR58D 210864 - REAR RIGHT FINAL DRIVE



**Sample No:** VCP422917  
**Oil Type:** VOLVO PREMIUM GEAR OIL 85W-140 GL-5  
**Job No:** 568333 TUCKER



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC  
 8418 PALM RIVER ROAD  
 TAMPA, FL  
 US 33619  
 Contact: KENNY HANEY  
 khaney@flaglerce.com  
 T: (813)630-0077  
 F: (813)630-2233



## SAMPLE INFORMATION

Sample Number	VCP422917	---	---	---
Sample Date	14 Jul 2023	---	---	---
Machine Hours	1534	---	---	---
Oil Hours	1000	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	ATTENTION	---	---	---



## OIL CONDITION

Visc @ 40°C	cSt	▲ 90.4	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	■ 37	---	---	---
Sodium	ppm	■ <1	---	---	---
Potassium	ppm	■ 3	---	---	---



## WEAR METALS

Iron	ppm	■ 440	---	---	---
Copper	ppm	■ 4	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ 0	---	---	---
Aluminum	ppm	■ 3	---	---	---
Chromium	ppm	■ 12	---	---	---
Molybdenum	ppm	■ 17	---	---	---
Nickel	ppm	■ 2	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 7	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	■ 3524	---	---	---
Magnesium	ppm	■ 10	---	---	---
Zinc	ppm	■ 721	---	---	---
Phosphorus	ppm	■ 544	---	---	---
Barium	ppm	■ 31	---	---	---
Boron	ppm	■ 16	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. Confirm oil type.

**Depot:** VOLVO0093  
**Unique No:** 10602499  
**Signed:** Don Baldrige  
**Report Date:** 14 Aug 2023



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

