



# CONSTRUCTION EQUIPMENT

326128 VOLVO A30G 752892 - BOGIE/CENTER AXLE



**Sample No:** VCP417354  
**Oil Type:** NOT GIVEN  
**Job No:** 326128



## SAMPLE INFORMATION

Sample Number	VCP417354	---	---	---
Sample Date	10 Aug 2023	---	---	---
Machine Hours	661	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

## ALTA EQUIPMENT

5985 COURT STREET ROAD  
SYRACUSE, NY  
US 13206  
Contact: JIM STRIGLE  
JIM.STRIGLE@ALTG.COM  
T: (315)437-2611  
F: (315)434-9471



## OIL CONDITION

Visc @ 40°C	cSt	█ 91.0	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	█ 6	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ 5	---	---	---



## WEAR METALS

Iron	ppm	█ 282	---	---	---
Copper	ppm	█ 14	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 1	---	---	---
Chromium	ppm	█ 6	---	---	---
Molybdenum	ppm	10	---	---	---
Nickel	ppm	█ 3	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	10	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	845	---	---	---
Magnesium	ppm	1	---	---	---
Zinc	ppm	359	---	---	---
Phosphorus	ppm	1356	---	---	---
Barium	ppm	5	---	---	---
Boron	ppm	279	---	---	---

## Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VOLVO0142  
**Unique No:** 10603749  
**Signed:** Wes Davis  
**Report Date:** 15 Aug 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

