



CONSTRUCTION EQUIPMENT

X58430 VOLVO ECR235EL 315285 - DIESEL EXHAUST FLUID (DEF)



Sample No: VCP413453
Oil Type: NOT GIVEN
Job No: X58430



SAMPLE INFORMATION

| | | | | |
|---------------|-------------|-----|-----|-----|
| Sample Number | VCP413453 | --- | --- | --- |
| Sample Date | 10 Aug 2023 | --- | --- | --- |
| Machine Hours | 0 | --- | --- | --- |
| Oil Hours | 0 | --- | --- | --- |
| Oil Changed | N/A | --- | --- | --- |
| Sample Status | NORMAL | --- | --- | --- |

SCOTT EQUIPMENT COMPANY LLC - Saint Rose
 PO BOX 997
 SAINT ROSE, LA
 US 70087
 Contact: DENISE CORVERS
 dcorvers@scottcompanies.com
 T: (504)461-0961
 F: (504)461-0970



CONTAMINATION

| | | | | | |
|-------------|--------|--|-----|-----|-----|
| Hydrocarbon | scalar | <input checked="" type="checkbox"/> NONE | --- | --- | --- |
|-------------|--------|--|-----|-----|-----|


DEF CONDITION

| | | | | | |
|------------------|--------|--|-----|-----|-----|
| Urea Content | % | <input checked="" type="checkbox"/> 32.8 | --- | --- | --- |
| Density @ 20°C | g/cm3 | <input checked="" type="checkbox"/> 1.0884 | --- | --- | --- |
| Refracting Index | | <input checked="" type="checkbox"/> 1.3829 | --- | --- | --- |
| Appearance | scalar | <input checked="" type="checkbox"/> Clear & Bright | --- | --- | --- |

Diagnosis

Fluid meets ISO 22241-2 requirements and is suitable for use. Appearance is acceptable. There is no indication of any contamination in the diesel exhaust fluid (def). Urea content is normal.

Depot: SCOSAI
Unique No: 10603809
Signed: Doug Bogart
Report Date: 16 Aug 2023



Sample Color & Clarity

