



CONSTRUCTION EQUIPMENT

SWO-064669 VOLVO A45G 352698 - COOLANT



Sample No: VCP405778
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: SWO-064669



SAMPLE INFORMATION

Sample Number	VCP405778	VCP408684	VCP367726	VCP388295
Sample Date	07 Aug 2023	16 May 2023	17 Jan 2023	12 Oct 2022
Machine Hours	4553	4038	3513	3026
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL



COOLANT CONDITION

pH	Scale 0-14	7.26	7.27	7.33	7.34
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	NT	NT	NT	NT
Percentage Glycol	%	45.1	45.1	45.0	44.5
Freezing Point	°C	-24	-24	-24	-21



CONTAMINATION

Coolant Appearance	normal	normal	normal	normal
Coolant Color	Yllow	Yllow	Yllow	Yllow

SAIIA CONSTRUCTION LLC

4400 LEWISBURG RD
BIRMINGHAM, AL
US 35207

Contact: STEPHANI BRITTON
sbritton@saiia.com;doug.bogart@wearcheck.com
T: (205)943-2268
F: (205)943-2269

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: SAIBIR
Unique No: 10603814
Signed: Doug Bogart
Report Date: 15 Aug 2023




CONSTRUCTION EQUIPMENT




VOLVO GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

