VOLVO

CONSTRUCTION EQUIPMENT X57615 KOBELCO CK1100 GH05-04032 - COOLANT



Sample No:VCP367311Oil Type:CONVENTIONAL COOLANTJob No:X57615

SAMPLE IN	FORMATION				
Sample Number	-	VCP367311			
Sample Date		09 Aug 2023			
Machine Hours		61537			
Sample Status		NORMAL			
COOLANT CONDITION					
рН	Scale 0-14	8.03			
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	372			
Percentage Glycol	%	49.9			
Freezing Point	°C	-33			
CONTAMINATION					
Coolant Appearance		normal			
Coolant Color		Green			



SCOTT EQUIPMENT COMPANY LLC - Saint Rose

PO BOX 997 SAINT ROSE, LA US 70087 Contact: DENISE CORVERS dcorvers@scottcompanies.com T: (504)461-0961 F: (504)461-0970

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot:SCOSAIUnique No:10605164Signed:Doug BogartReport Date:16 Aug 2023


CONSTRUCTION EQUIPMENT



GRAPHS

Iron/Tin/Silver

VOLVO



Contact/Location: DENISE CORVERS - SCOSAI