



CONSTRUCTION EQUIPMENT

SWA275711-10 VOLVO L70H 623404 - COOLANT



Sample No: VCP396049
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: SWA275711-10



SAMPLE INFORMATION

Sample Number	VCP396049	VCP367841	VCP376096	VCP322248
Sample Date	09 Jun 2023	15 Dec 2022	15 Aug 2022	16 May 2022
Machine Hours	8270	7328	6731	6283
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

DENALI WE CARE

400 TORNE RD
HILLBURN, NY
US 10931
Contact: Service Manager



COOLANT CONDITION

pH	Scale 0-14	7.01	7.02	7.01	7.06
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	0	NT	0	0
Percentage Glycol	%	51.4	51.1	50.9	50.7
Freezing Point	°C	-38	-38	-35	-35

T:
F:

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	normal	normal	normal
Coolant Color	Yllow	Yllow	Yllow	Yllow

Depot: DENHIL
Unique No: 10605165
Signed: Doug Bogart
Report Date: 16 Aug 2023




CONSTRUCTION EQUIPMENT




VOLVO GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

