

CONSTRUCTION EQUIPMENT Shipping Belt 1 - Gearbox



Sample No:VCE155573Oil Type:NOT GIVEN

Job No:

Boron

	INFORMATIO	N	 	
	. INFUKMATIUI			<u>-</u>
Sample Number		VCE155573	 	
Sample Date		15 Aug 2023	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	145	 	
VISC @ 40 C	CSI	145		
VOLVO				
CONTAM	IINATION			
Silicon	ppm	4 9	 	
Sodium	ppm	0	 	
Potassium	ppm	■ <1	 	
VOLVO	ETAL C			
V WEAR M			 -	-
Iron	ppm	11	 	
Copper	ppm		 	
Lead	ppm	■ <1	 	
Tin	ppm	0	 	
Aluminum	ppm	0	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	<1	 	
Manganese	ppm	<1	 	
Vanadium	ppm	0	 	
	ES		 	
Calcium	ppm	225	 	
Magnesium	ppm	<1	 	
Zinc	ppm	101	 	
Phosphorus	ppm	506	 	
Barium	ppm	1	 	
Poron	ppm	4		



AMG RESOURCES CORP

1303 RED ROCK RD ST PAUL, MN US 55119 Contact: KEITH SMITH amg-keith@msn.com T: (651)739-6080 F: (651)739-6066

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:AMGPITUnique No:10605600Signed:Jonathan HesterReport Date:17 Aug 2023


ppm

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: AMGPIT [WUSCAR] 05925653 (Generated: 08/17/2023 12:39:42) Rev: 1

Contact/Location: KEITH SMITH - AMGPIT