



# CONSTRUCTION EQUIPMENT

## VOLVO EC350EL 310558 - DIESEL ENGINE



**Sample No:** VCP0007511  
**Oil Type:** DIESEL ENGINE OIL SAE 30  
**Job No:**



### SAMPLE INFORMATION

Sample Number	VCP0007511	---	---	---
Sample Date	11 Aug 2023	---	---	---
Machine Hours	0	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

**ALTA EQUIPMENT COMPANY**  
 8750 PHILIPS HWY  
 JACKSONVILLE, FL  
 US 32256  
 Contact: SHAWN NORTHCRAFT  
 shawn.northcraft@altg.com  
 T: (904)737-6000  
 F: (904)737-1260



### OIL CONDITION

Visc @ 100°C	cSt	█ 12.3	---	---	---
Base Number (BN)	mg KOH/g	█ 9.9	---	---	---
Oxidation (PA)	%	78	---	---	---

### Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DIESEL ENGINE OIL SAE 30. Please confirm.  
 All component wear rates are normal. Light fuel dilution occurring. No other contaminants were detected in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



### CONTAMINATION

Soot %	%	█ 0.1	---	---	---
Nitration (PA)	%	57	---	---	---
Sulfation (PA)	%	58	---	---	---
Glycol	%	NEG	---	---	---
Fuel	%	█ 2.3	---	---	---
Silicon	ppm	█ 5	---	---	---
Sodium	ppm	█ 4	---	---	---
Potassium	ppm	█ 2	---	---	---



### WEAR METALS

Iron	ppm	█ 3	---	---	---
Copper	ppm	█ 1	---	---	---
Lead	ppm	█ 1	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 42	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	█ 0	---	---	---
Silver	ppm	█ <1	---	---	---
Manganese	ppm	█ <1	---	---	---
Vanadium	ppm	<1	---	---	---



### ADDITIVES

Calcium	ppm	█ 1774	---	---	---
Magnesium	ppm	█ 531	---	---	---
Zinc	ppm	█ 1139	---	---	---
Phosphorus	ppm	█ 924	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 45	---	---	---

**Depot:** VOLVO0092  
**Unique No:** 10605660  
**Signed:** Wes Davis  
**Report Date:** 17 Aug 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

