



CONSTRUCTION EQUIPMENT

WO7013189-2 VOLVO EC250E 310555 - REAR RIGHT FINAL DRIVE



Sample No: VCP409367
Oil Type: GEAR OIL SAE 80W90
Job No: WO7013189-2



McClung-Logan Virginia LLC- RICHMOND
 1345 MOUNTAIN ROAD
 GLEN ALLEN, VA
 US 23060
 Contact: KYLE RATLIFFE
 KRATLIFFE@MCCLUNG-LOGAN.COM
 T:
 F: (804)266-1611



SAMPLE INFORMATION

Sample Number	VCP409367	VCP409405	---	---
Sample Date	14 Aug 2023	09 Aug 2023	---	---
Machine Hours	1842	1841	---	---
Oil Hours	1	1841	---	---
Oil Changed	Not Chngd	Changed	---	---
Sample Status	ATTENTION	NORMAL	---	---



OIL CONDITION

Visc @ 40°C	cSt	▲ 58.8	■ 157	---	---
-------------	-----	---------------	-------	-----	-----



CONTAMINATION

Silicon	ppm	■ 8	■ 65	---	---
Sodium	ppm	■ 2	■ 3	---	---
Potassium	ppm	■ 1	■ 2	---	---



WEAR METALS

Iron	ppm	■ 81	■ 556	---	---
Copper	ppm	■ 0	■ <1	---	---
Lead	ppm	■ 0	■ 0	---	---
Tin	ppm	■ <1	■ <1	---	---
Aluminum	ppm	■ 2	■ 7	---	---
Chromium	ppm	■ 1	■ 9	---	---
Molybdenum	ppm	■ 1	■ 19	---	---
Nickel	ppm	■ <1	■ <1	---	---
Titanium	ppm	<1	1	---	---
Silver	ppm	0	0	---	---
Manganese	ppm	■ 1	■ 6	---	---
Vanadium	ppm	0	<1	---	---



ADDITIVES

Calcium	ppm	■ 94	■ 671	---	---
Magnesium	ppm	■ 30	■ 219	---	---
Zinc	ppm	■ 53	■ 413	---	---
Phosphorus	ppm	■ 2279	■ 860	---	---
Barium	ppm	■ 0	■ 0	---	---
Boron	ppm	■ 257	■ 86	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. Confirm oil type.

Depot: VOLVO8882
Unique No: 10606349
Signed: Don Baldrige
Report Date: 17 Aug 2023



CONSTRUCTION EQUIPMENT



GRAPHS

