

# CONSTRUCTION EQUIPMENT VOLVO A45G 342539 - FRONT AXLE



Sample No: VCP0007498
Oil Type: {unknown}

Job No:

| SAMPLE        | E INFORMATION | ı           |      |  |
|---------------|---------------|-------------|------|--|
| Sample Number | -             | VCP0007498  | <br> |  |
| Sample Date   |               | 11 Aug 2023 | <br> |  |
| Machine Hours |               | 0           | <br> |  |
| Oil Hours     |               | 0           | <br> |  |
| Oil Changed   |               | N/A         | <br> |  |
| Sample Status |               | NORMAL      | <br> |  |
|               |               |             |      |  |
| OIL CON       | DITION        |             |      |  |
| Visc @ 40°C   | cSt           | <b>293</b>  | <br> |  |
|               |               | _           |      |  |
| VOLVO         | AINATION      |             |      |  |
| _             | MINATION      |             |      |  |
| Silicon       | ppm           | ■8          | <br> |  |
| Sodium        | ppm           | <b>■</b> 1  | <br> |  |
| Potassium     | ppm           | <b>2</b>    | <br> |  |
| VOLVO         |               |             |      |  |
| WEAR N        | METALS        |             |      |  |
| Iron          | ppm           | ■20         | <br> |  |
| Copper        | ppm           | <b>■</b> <1 | <br> |  |
| Lead          | ppm           | ■0          | <br> |  |
| Tin           | ppm           | <b>0</b>    | <br> |  |
| Aluminum      | ppm           | ■0          | <br> |  |
| Chromium      | ppm           | <b>■</b> <1 | <br> |  |
| Molybdenum    | ppm           | 5           | <br> |  |
| Nickel        | ppm           | ■0          | <br> |  |
| Titanium      | ppm           | 0           | <br> |  |
| Silver        | ppm           | 0           | <br> |  |
| Manganese     | ppm           | 4           | <br> |  |
| Vanadium      | ppm           | 0           | <br> |  |
| VOLVO         |               |             |      |  |
| ADDITIV       | VES           |             |      |  |
| Calcium       | ppm           | 66          | <br> |  |
| Magnesium     | ppm           | 34          | <br> |  |
| Zinc          | ppm           | 57          | <br> |  |
| Phosphorus    | ppm           | 916         | <br> |  |
| Barium        | ppm           | 0           | <br> |  |
| Boron         | ppm           | 177         | <br> |  |



### **ALTA EQUIPMENT COMPANY**

8750 PHILIPS HWY JACKSONVILLE, FL US 32256

Contact: TECHNICIAN ACCOUNT catherine.anastasio@wearcheck.com T:

F: (904)737-1260

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0092Unique No:10606414Signed:Don BaldridgeReport Date:17 Aug 2023

Submitted By: TECHNICIAN ACCOUNT



# **CONSTRUCTION EQUIPMENT**





#### GRAPHS

