



# CONSTRUCTION EQUIPMENT

## X47387 VOLVO A25G 752487 - TRANSMISSION (AUTO)



**Sample No:** VCP427003  
**Oil Type:** VOLVO AUTOMATIC TRANSMISSION FLUID AT102  
**Job No:** X47387



**SCOTT EQUIPMENT COMPANY LLC - Lake Charles**  
 PO BOX 16955  
 LAKE CHARLES, LA  
 US 70616  
 Contact: SAMANTHA SOILEAU  
 ssoileau@scottcompanies.com  
 T: (337)433-9811  
 F: (318)433-6623



### SAMPLE INFORMATION

Sample Number	VCP427003	---	---	---
Sample Date	09 Aug 2023	---	---	---
Machine Hours	1928	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---



### OIL CONDITION

Visc @ 40°C	cSt	█ 30.3	---	---	---
-------------	-----	--------	-----	-----	-----



### CONTAMINATION

Silicon	ppm	█ 15	---	---	---
Sodium	ppm	█ 5	---	---	---
Potassium	ppm	█ 2	---	---	---



### WEAR METALS

Iron	ppm	█ 28	---	---	---
Copper	ppm	█ 15	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 4	---	---	---
Aluminum	ppm	█ 19	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	█ 0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 3	---	---	---
Vanadium	ppm	█ 0	---	---	---



### ADDITIVES

Calcium	ppm	█ 72	---	---	---
Magnesium	ppm	█ 1	---	---	---
Zinc	ppm	█ 0	---	---	---
Phosphorus	ppm	█ 181	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 76	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

**Depot:** VOLVO6244  
**Unique No:** 10606420  
**Signed:** Wes Davis  
**Report Date:** 17 Aug 2023



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

