



CONSTRUCTION EQUIPMENT

VOLVO A30G 342569 - REAR TRANSMISSION (AUTO)



Sample No: VCP422768
Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102
Job No:



SAMPLE INFORMATION

Sample Number	VCP422768	---	---	---
Sample Date	12 Jul 2023	---	---	---
Machine Hours	5895	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

RIPA AND ASSOCIATES

10149 FISHER AVENUE
TAMPA, FL
US 33619
Contact: ROBERT TURNER
rturner@ripatampa.com
T:
F:



OIL CONDITION

Visc @ 40°C	cSt	█ 28.4	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 3	---	---	---
Sodium	ppm	█ 5	---	---	---
Potassium	ppm	█ <1	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 14	---	---	---
Copper	ppm	█ 9	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 2	---	---	---
Aluminum	ppm	█ 9	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	█ 0	---	---	---
Silver	ppm	█ <1	---	---	---
Manganese	ppm	█ <1	---	---	---
Vanadium	ppm	█ 0	---	---	---



ADDITIVES

Calcium	ppm	█ 72	---	---	---
Magnesium	ppm	█ 2	---	---	---
Zinc	ppm	█ 0	---	---	---
Phosphorus	ppm	█ 189	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 93	---	---	---

Depot: RIPTAM
Unique No: 10606425
Signed: Wes Davis
Report Date: 17 Aug 2023



CONSTRUCTION EQUIPMENT



GRAPHS

