



# CONSTRUCTION EQUIPMENT

10654 WM VOLVO EC300EL 310989 - COOLANT



**Sample No:** VCP412026  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:** 10654 WM



## SAMPLE INFORMATION

Sample Number	VCP412026	---	---	---
Sample Date	14 Aug 2023	---	---	---
Machine Hours	4798	---	---	---
Sample Status	NORMAL	---	---	---

**HOFFMAN EQUIPMENT - LIONVILLE**  
 120 GORDON DRIVE  
 LIONVILLE, PA  
 US 19341  
 Contact: JIM FEHR  
 jim.fehr@hoffmanequip.com  
 T: (610)363-9200  
 F: (610)594-0829



## COOLANT CONDITION

pH	Scale 0-14	■ 7.53	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 0	---	---	---
Percentage Glycol	%	■ 54.0	---	---	---
Freezing Point	°C	■ -45	---	---	---

## Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



## CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Orange	---	---	---

**Depot:** VOLVO8879  
**Unique No:** 10606912  
**Signed:** Doug Bogart  
**Report Date:** 18 Aug 2023



# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity




### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

