

CONSTRUCTION EQUIPMENT VOLVO EC480EL 314981 - COOLANT



Sample No: VCP369307

Oil Type:	VOLVO COOLANT VCS (YELLOW)
-----------	----------------------------

Job No:

SAMPLE INFORMATION							
Sample Number	-	VCP369307					
Sample Date		07 Aug 2023					
Machine Hours		1929					
Sample Status		NORMAL					
COOLANT CONDITION							
рН	Scale 0-14	7.56					
Reserve Alkalinity	Scale 0-20						
Nitrites	ppm	NT					
Percentage Glycol	%	51.4					
Freezing Point	°C	-38					
CONTAMIN	ATION						
Coolant Appearance		normal					
Coolant Color		Yllow					



SAIIA CONSTRUCTION LLC

4400 LEWISBURG RD BIRMINGHAM, AL US 35207 Contact: STEPHANI BRITTON sbritton@saiia.com;doug.bogart@wearcheck.com T: (205)943-2268 F: (205)943-2269

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot:SAIBIRUnique No:10607629Signed:Jonathan HesterReport Date:22 Aug 2023


CONSTRUCTION EQUIPMENT



GRAPHS

Iron/Tin/Silver

VOLVO



Report Id: SAIBIR [WUSCAR] 05927682 (Generated: 08/22/2023 11:16:27) Rev: 1

Contact/Location: STEPHANI BRITTON - SAIBIR