



CONSTRUCTION EQUIPMENT

SPM593879 ALTER ROCK SENNEBOGEN 835 835.0.2740 - FRONT AXLE



Sample No: VCP423495
Oil Type: GEAR OIL SAE 80W90
Job No: SPM593879 ALTER ROCK



SAMPLE INFORMATION

Sample Number	VCP423495	---	---	---
Sample Date	11 Aug 2023	---	---	---
Machine Hours	6443	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

ALTA CONSTRUCTION EQUIPMENT

613 E STEVENSON RD
OTTAWA, IL
US 61350
Contact: ALEX MARCO
ALEXANDER.MARCO@ALTG.COM
T:
F:



OIL CONDITION

Visc @ 40°C	cSt	█ 148	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 2	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ 0	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 3	---	---	---
Copper	ppm	█ 5	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 0	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 4	---	---	---
Magnesium	ppm	█ < 1	---	---	---
Zinc	ppm	█ 8	---	---	---
Phosphorus	ppm	█ 1909	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 147	---	---	---

Depot: VOLVO5055
Unique No: 10608999
Signed: Sean Felton
Report Date: 21 Aug 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

