



# CONSTRUCTION EQUIPMENT

SPM593006 SENNEBOGEN 840ME 840.0.2170 - REAR LEFT FINAL DRIVE



**Sample No:** VCP399752  
**Oil Type:** GEAR OIL SAE 80W90  
**Job No:** SPM593006



## SAMPLE INFORMATION

Sample Number	VCP399752	VCP299445	---	---
Sample Date	14 Aug 2023	15 Jul 2021	---	---
Machine Hours	8508	3424	---	---
Oil Hours	0	0	---	---
Oil Changed	Changed	Changed	---	---
Sample Status	NORMAL	NORMAL	---	---

## ALTA CONSTRUCTION EQUIPMENT

613 E STEVENSON RD

OTTAWA, IL

US 61350

Contact: ALEX MARCO

ALEXANDER.MARCO@ALTG.COM

T:

F:



## OIL CONDITION

Visc @ 40°C	cSt	█ 148	█ 133	---	---
-------------	-----	-------	-------	-----	-----



## CONTAMINATION

Silicon	ppm	█ 2	█ 1	---	---
Sodium	ppm	█ 0	█ <1	---	---
Potassium	ppm	█ 0	█ 0	---	---



## WEAR METALS

Iron	ppm	█ 13	█ 15	---	---
Copper	ppm	█ 2	█ 2	---	---
Lead	ppm	█ 0	█ 2	---	---
Tin	ppm	█ 0	█ 0	---	---
Aluminum	ppm	█ 0	█ <1	---	---
Chromium	ppm	█ 0	█ <1	---	---
Molybdenum	ppm	█ 0	█ 1	---	---
Nickel	ppm	█ 0	█ 0	---	---
Titanium	ppm	█ 0	█ 0	---	---
Silver	ppm	█ 0	█ <1	---	---
Manganese	ppm	█ <1	█ <1	---	---
Vanadium	ppm	█ 0	█ <1	---	---



## ADDITIVES

Calcium	ppm	█ 4	█ 6	---	---
Magnesium	ppm	█ 1	█ 0	---	---
Zinc	ppm	█ 7	█ 4	---	---
Phosphorus	ppm	█ 2056	█ 916	---	---
Barium	ppm	█ 0	█ <1	---	---
Boron	ppm	█ 126	█ 157	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VOLVO5055

**Unique No:** 10609003

**Signed:** Sean Felton

**Report Date:** 21 Aug 2023



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

