



CONSTRUCTION EQUIPMENT

VOLVO L70H L70H 623170 - COOLANT



Sample No: VCP0008014

Oil Type: {unknown}

Job No:



SAMPLE INFORMATION

Sample Number	VCP0008014	---	---	---
Sample Date	15 Aug 2023	---	---	---
Machine Hours	0	---	---	---
Sample Status	NORMAL	---	---	---



COOLANT CONDITION

pH	Scale 0-14	■ 7.66	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 48.6	---	---	---
Freezing Point	°C	■ -31	---	---	---



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---



ALTA EQUIPMENT COMPANY

8750 PHILIPS HWY
JACKSONVILLE, FL
US 32256

Contact: TECHNICIAN ACCOUNT
catherine.anastasio@wearcheck.com

T:
F: (904)737-1260

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: VOLVO0092
Unique No: 10609059
Signed: Jonathan Hester
Report Date: 22 Aug 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

