



# CONSTRUCTION EQUIPMENT

## VOLVO A30G 752893 - DROP BOX



**Sample No:** VCP427091

**Oil Type:** NOT GIVEN

**Job No:**



### SAMPLE INFORMATION

Sample Number	VCP427091	---	---	---
Sample Date	20 Aug 2023	---	---	---
Machine Hours	611	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC  
 8418 PALM RIVER ROAD  
 TAMPA, FL  
 US 33619  
 Contact: KENNY HANEY  
 khaney@flaglerce.com  
 T: (813)630-0077  
 F: (813)630-2233



### OIL CONDITION

Visc @ 40°C	cSt	█ 47.2	---	---	---
-------------	-----	--------	-----	-----	-----



### CONTAMINATION

Silicon	ppm	█ 25	---	---	---
Sodium	ppm	█ 6	---	---	---
Potassium	ppm	█ 3	---	---	---



### WEAR METALS

Iron	ppm	█ 47	---	---	---
Copper	ppm	█ <1	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 4	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	1	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	2	---	---	---
Vanadium	ppm	0	---	---	---



### ADDITIVES

Calcium	ppm	50	---	---	---
Magnesium	ppm	3	---	---	---
Zinc	ppm	47	---	---	---
Phosphorus	ppm	3150	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	317	---	---	---

### Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VOLVO0093  
**Unique No:** 10615328  
**Signed:** Sean Felton  
**Report Date:** 23 Aug 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

