



CONSTRUCTION EQUIPMENT

306982 VOLVO A30G 752893 - TRANSMISSION (AUTO)



Sample No: VCP427097

Oil Type: DEXRON III

Job No: 306982



SAMPLE INFORMATION

Sample Number	VCP427097	---	---	---
Sample Date	12 Jul 2023	---	---	---
Machine Hours	611	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
 8418 PALM RIVER ROAD
 TAMPA, FL
 US 33619
 Contact: KENNY HANEY
 khaney@flaglerce.com
 T: (813)630-0077
 F: (813)630-2233



OIL CONDITION

Visc @ 40°C	cSt	█ 29.4	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 15	---	---	---
Sodium	ppm	█ 4	---	---	---
Potassium	ppm	█ 2	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 21	---	---	---
Copper	ppm	█ 16	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 2	---	---	---
Aluminum	ppm	█ 14	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 3	---	---	---
Vanadium	ppm	<1	---	---	---



ADDITIVES

Calcium	ppm	█ 68	---	---	---
Magnesium	ppm	█ <1	---	---	---
Zinc	ppm	█ 0	---	---	---
Phosphorus	ppm	█ 187	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 96	---	---	---

Depot: VOLVO0093
Unique No: 10615355
Signed: Sean Felton
Report Date: 23 Aug 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

