



CONSTRUCTION EQUIPMENT

VOLVO A30G 742515 - COOLANT



Sample No: VCP412960
Oil Type: CHEVRON DELO EXTENDED LIFE COOLANT
Job No:



SAMPLE INFORMATION

Sample Number	VCP412960	---	---	---
Sample Date	17 Aug 2023	---	---	---
Machine Hours	2000	---	---	---
Sample Status	NORMAL	---	---	---

DH FUNK AND SONS LLC
 3995 CONTINENTAL DRIVE
 COLUMBIA, PA
 US 17512
 Contact: GARY SHEPHERD
 GSHEPHERD@DHFUNK.COM



COOLANT CONDITION

pH	Scale 0-14	■ 7.37	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 0	---	---	---
Percentage Glycol	%	■ 50.4	---	---	---
Freezing Point	°C	■ -35	---	---	---

T:
F:

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	LtRed	---	---	---

Depot: DHFCOL
Unique No: 10615375
Signed: Doug Bogart
Report Date: 22 Aug 2023




CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver



Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

