

## **CONSTRUCTION EQUIPMENT**

SW-22427-2 GRANT MAC VOLVO EC750EHR 391021 - REAR LEFT

Sample No: VCP354248

Oil Type: VOLVO PREMIUM GEAR OIL 80W-90 GL-5

**Job No:** SW-22427-2 GRANT MAC

CVMDILI	NFORMATION				
	NFURMATION				
Sample Number		VCP354248			
Sample Date		14 Aug 2023			
Machine Hours		2115			
Oil Hours		2115			
Oil Changed		Changed			
Sample Status		NORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	<b>166</b>			
VISC @ 40 C	CSI	<b>100</b>			
VOLVO					
CONTAMI	NATION				
Silicon	ppm	<b>2</b> 4			
Sodium	ppm	<b>2</b>			
Potassium	ppm	■4			
WEAR METALS					
_	: IMF2				
Iron	ppm	■ 320			
Copper	ppm	<b>■</b> <1			
Lead	ppm	■0			
Tin	ppm	<b>■</b> 0			
Aluminum	ppm	■3			
Chromium	ppm	<b>■</b> 4			
Molybdenum	ppm	<b>■</b> <1			
Nickel	ppm	<b>■</b> <1			
Titanium	ppm	<1			
Silver	ppm	0			
Manganese	ppm	<b>6</b>			
Vanadium	ppm	0			
ADDITIVE	2				
Calcium	ppm	<b>21</b>			
Magnesium	ppm	<b>■</b> 0			
Zinc	ppm	<b>6</b>			
Phosphorus	ppm	■329			
Barium	ppm	<b>6</b>			
Boron	ppm	<b>0</b>			



### ARNOLD MACHINERY COMPANY

2975 WEST 2100 SOUTH SALT LAKE CITY, UT US 84119 Contact: TONY PAYAN tpayan@arnoldmachinery.com T: (801)972-4000

#### Diagnosis

F: (801)975-9434

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO8770Unique No:10616438Signed:Don BaldridgeReport Date:23 Aug 2023



# **CONSTRUCTION EQUIPMENT**





