



CONSTRUCTION EQUIPMENT

VOLVO L70G L70G 2307 - COOLANT



Sample No: VCP0008026
Oil Type: HYBRID (HOAT) COOLANT
Job No:



SAMPLE INFORMATION

Sample Number	VCP0008026	---	---	---
Sample Date	18 Aug 2023	---	---	---
Machine Hours	0	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT COMPANY
 8750 PHILIPS HWY
 JACKSONVILLE, FL
 US 32256
 Contact: TECHNICIAN ACCOUNT
 catherine.anastasio@wearcheck.com
 T:
 F: (904)737-1260



COOLANT CONDITION

pH	Scale 0-14	■ 7.85	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 260	---	---	---
Percentage Glycol	%	■ 50.3	---	---	---
Freezing Point	°C	■ -35	---	---	---

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. Glycol and nitrite levels are acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

Depot: VOLVO0092
Unique No: 10616552
Signed: Doug Bogart
Report Date: 24 Aug 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

