



# CONSTRUCTION EQUIPMENT

594089 DIPRO VOLVO L220H 3352 - COOLANT



**Sample No:** VCP411737  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:** 594089 DIPRO



## SAMPLE INFORMATION

Sample Number	VCP411737	---	---	---
Sample Date	14 Aug 2023	---	---	---
Machine Hours	6368	---	---	---
Sample Status	NORMAL	---	---	---

**ALTA EQUIPMENT COMPANY - METRO WEST**  
 56195 PONTIAC TRAIL  
 NEW HUDSON, MI  
 US 48165  
 Contact: PAUL CONZ  
 paul.conz@altg.com  
 T: (313)348-8861  
 F: (248)356-2029



## COOLANT CONDITION

pH	Scale 0-14	■ 7.11	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 0	---	---	---
Percentage Glycol	%	■ 47.2	---	---	---
Freezing Point	°C	■ -28	---	---	---

## Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



## CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

**Depot:** VOLVO2990  
**Unique No:** 10617085  
**Signed:** Doug Bogart  
**Report Date:** 24 Aug 2023



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

