



# CONSTRUCTION EQUIPMENT

9483 WASTE MGMT VOLVO L70G 614434 - COOLANT



**Sample No:** VCP413678  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:** 9483 WASTE MGMT



## SAMPLE INFORMATION

Sample Number	VCP413678	---	---	---
Sample Date	16 Aug 2023	---	---	---
Machine Hours	22133	---	---	---
Sample Status	NORMAL	---	---	---

**MCCLUNG-LOGAN EQUIPMENT CO INC MAIN**  
4601 WASHINGTON BOULEVARD  
BALTIMORE, MD  
US 21227  
Contact: MARK CIULLA  
mciulla@mcclung-logan.com  
T: (410)242-6500  
F: (410)242-7835



## COOLANT CONDITION

pH	Scale 0-14	■ 7.46	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 0	---	---	---
Percentage Glycol	%	■ 53.5	---	---	---
Freezing Point	°C	■ -43	---	---	---

## Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



## CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

**Depot:** VOLVO0150  
**Unique No:** 10617089  
**Signed:** Doug Bogart  
**Report Date:** 24 Aug 2023




# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity




### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

