

## **CONSTRUCTION EQUIPMENT**

SPM594625 VOLVO EC750E 314108 - HYDRAULIC SYSTEM

Sample No: VCP413421

Oil Type: VOLVO SUPER HYDRAULIC OIL 46

**Job No:** SPM594625





ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

WEAR METALS								
Iron	ppm	<b>□</b> 7						
Copper	ppm	<b>15</b>						
Lead	ppm	<b>■&lt;1</b>						
Tin	ppm	<b>■</b> 0						
Aluminum	ppm	<b>■</b> <1						
Chromium	ppm	■0						
Molybdenum	ppm	<b>0</b>						
Nickel	ppm	<b>■</b> 0						
Titanium	ppm	0						
Silver	ppm	0						
Manganese	ppm	<b>■</b> <1						
Vanadium	ppm	<1						

ADDITION								
Calcium	ppm	■82						
Magnesium	ppm	<b></b>						
Zinc	ppm	<b>471</b>						
Phosphorus	ppm	■374						
Barium	ppm	<b>0</b>						
Boron	ppm	<b>■</b> 0						

Depot:VOLVO0093Unique No:10617373Signed:Wes DavisReport Date:24 Aug 2023



## **CONSTRUCTION EQUIPMENT**





## GRAPHS

