



CONSTRUCTION EQUIPMENT

SPM594625 VOLVO EC750E 314108 - LEFT SWING DRIVE



Sample No: VCP413420
Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5
Job No: SPM594625



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
 8418 PALM RIVER ROAD
 TAMPA, FL
 US 33619
 Contact: KENNY HANEY
 khaney@flaglerce.com
 T: (813)630-0077
 F: (813)630-2233



SAMPLE INFORMATION

Sample Number	VCP413420	---	---	---
Sample Date	17 Aug 2023	---	---	---
Machine Hours	2059	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	█ 173	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 12	---	---	---
Sodium	ppm	█ <1	---	---	---
Potassium	ppm	█ <1	---	---	---



WEAR METALS

Iron	ppm	█ 729	---	---	---
Copper	ppm	█ 14	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 3	---	---	---
Chromium	ppm	█ 11	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 11	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 22	---	---	---
Magnesium	ppm	█ <1	---	---	---
Zinc	ppm	█ 23	---	---	---
Phosphorus	ppm	█ 261	---	---	---
Barium	ppm	█ 1	---	---	---
Boron	ppm	█ 0	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0093
Unique No: 10617626
Signed: Jonathan Hester
Report Date: 25 Aug 2023



CONSTRUCTION EQUIPMENT



GRAPHS

