



CONSTRUCTION EQUIPMENT

VOLVO A40D 70322 - REAR AXLE



Sample No: VCP419856
Oil Type: MOBIL MOBILUBE HD 80W90
Job No:



SAMPLE INFORMATION

Sample Number	VCP419856	VCP378092	VCP360997	VCP347991
Sample Date	01 Aug 2023	16 Sep 2022	16 Jun 2022	11 May 2022
Machine Hours	26925	25375	24817	24564
Oil Hours	991	558	1051	798
Oil Changed	Changed	Not Changd	Changed	Not Changd
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

SCHILDBERG CONSTRUCTION COMPANY
 PO BOX 358
 GREENFIELD, IA
 US 50849
 Contact: SCOTT ARMSTRONG
 sarmstrong@schildberg.com
 T: (641)743-8237
 F: (641)743-2486



OIL CONDITION

Visc @ 40°C	cSt	134	137	138	138
-------------	-----	------------	-----	-----	-----



CONTAMINATION

Silicon	ppm	2	1	1	2
Sodium	ppm	0	0	<1	<1
Potassium	ppm	<1	0	0	<1



WEAR METALS

Iron	ppm	36	15	19	15
Copper	ppm	<1	<1	<1	<1
Lead	ppm	0	0	0	0
Tin	ppm	0	0	0	0
Aluminum	ppm	0	0	<1	<1
Chromium	ppm	0	0	0	0
Molybdenum	ppm	1	<1	1	1
Nickel	ppm	0	0	0	0
Titanium	ppm	0	0	0	0
Silver	ppm	0	0	0	<1
Manganese	ppm	<1	<1	<1	<1
Vanadium	ppm	0	0	0	0



ADDITIVES

Calcium	ppm	198	173	188	193
Magnesium	ppm	8	6	14	15
Zinc	ppm	86	72	91	90
Phosphorus	ppm	1023	983	926	1014
Barium	ppm	0	0	0	0
Boron	ppm	216	170	159	163

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: SCHGRE
Unique No: 10617693
Signed: Wes Davis
Report Date: 24 Aug 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

