



# CONSTRUCTION EQUIPMENT

SWO-064855 VOLVO A45G 352915 - COOLANT



**Sample No:** VCP427494  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:** SWO-064855



## SAMPLE INFORMATION

Sample Number	<b>VCP427494</b>	VCP414107	VCP397695	VCP365954
Sample Date	<b>15 Aug 2023</b>	26 May 2023	19 Jan 2023	28 Sep 2022
Machine Hours	<b>2344</b>	1912	1420	978
Sample Status	<b>NORMAL</b>	NORMAL	NORMAL	NORMAL



## COOLANT CONDITION

pH	Scale 0-14	<b>7.38</b>	7.50	7.58	7.88
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	<b>NT</b>	NT	NT	NT
Percentage Glycol	%	<b>43.9</b>	43.9	44.0	43.4
Freezing Point	°C	<b>-19</b>	-19	-21	-19



## CONTAMINATION

Coolant Appearance	<b>normal</b>	normal	normal	normal
Coolant Color	<b>Yllow</b>	Yllow	Yllow	Yllow

### SAIIA CONSTRUCTION LLC

4400 LEWISBURG RD  
BIRMINGHAM, AL  
US 35207

Contact: STEPHANI BRITTON  
sbritton@saiia.com;doug.bogart@wearcheck.com  
T: (205)943-2268  
F: (205)943-2269

### Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

**Depot:** SAIBIR  
**Unique No:** 10617794  
**Signed:** Doug Bogart  
**Report Date:** 26 Aug 2023




# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity




### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

