CONSTRUCTION EQUIPMENT SWA329522-10 VOLVO EC350E 314471 - COOLANT



Sample No:VCP434834Oil Type:VOLVO COOLANT VCS (YELLOW)

Job No:

SWA329522-10

SAMPLE INFORMATION

VOLVO

VCP434834	VCP390754	VCP367847	
19 Aug 2023	09 May 2023	06 Dec 2022	
1649	1001	577	
NORMAL	NORMAL	NORMAL	
N			
-14 7.65	7.86	8.06	
-20			
NT NT	NT	NT	
48.0	47.7	47.7	
- 31	28	28	
normal	normal	normal	
Yllow	Yllow	Yllow	
	19 Aug 2023 1649 NORMAL 14 7.65 NT 48.0 31	19 Aug 2023 09 May 2023 1649 1001 NORMAL NORMAL 14 7.65 7.86 -20 NT NT NT 48.0 47.7 -31 -28 normal	19 Aug 2023 09 May 2023 06 Dec 2022 1649 1001 577 NORMAL NORMAL NORMAL 14 7.65 7.86 8.06 -20 NT NT NT NT 48.0 47.7 47.7 -31 -28 -28 normal normal normal



CALLANAN INDUSTRIES

93 SULLIVAN RD MONTICELLO, NY US 12701 Contact: Service Manager

T: F:

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot:CALMONNYUnique No:10617796Signed:Doug BogartReport Date:26 Aug 2023


CONSTRUCTION EQUIPMENT




GRAPHS

Iron/Tin/Silver

VOLVO




⊂ _______ Copper/Aluminum/Lead



Reserve Alkalinity

Nitrites



Report Id: CALMONNY [WUSCAR] 05932525 (Generated: 08/28/2023 17:04:31) Rev: 1

Contact/Location: Service Manager - CALMONNY