



CONSTRUCTION EQUIPMENT

SWA303245-20 VOLVO L110H 631591 - COOLANT



Sample No: VCP407106
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: SWA303245-20



SAMPLE INFORMATION

Sample Number	VCP407106	VCP419921	VCP374132	VCP316964
Sample Date	28 Jul 2023	27 Feb 2023	06 Jun 2022	21 Feb 2022
Machine Hours	7541	6936	5936	5432
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL



DENALI WE CARE

400 TORNE RD
HILLBURN, NY
US 10931
Contact: Service Manager



COOLANT CONDITION

pH	Scale 0-14	7.44	7.64	7.49	7.54
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	NT	NT	0	NT
Percentage Glycol	%	53.2	53.1	53.0	52.8
Freezing Point	°C	-43	-43	-43	-40

T:
F:



CONTAMINATION

Coolant Appearance	normal	normal	normal	normal
Coolant Color	Yllow	Yllow	Yllow	Yllow

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: DENHIL
Unique No: 10617798
Signed: Doug Bogart
Report Date: 26 Aug 2023




CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

