



CONSTRUCTION EQUIPMENT

337829 VOLVO A30G 742652 - COOLANT



Sample No: VCP407695
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: 337829



SAMPLE INFORMATION

Sample Number	VCP407695	---	---	---
Sample Date	18 Aug 2023	---	---	---
Machine Hours	2056	---	---	---
Sample Status	NORMAL	---	---	---



COOLANT CONDITION

pH	Scale 0-14	■ 7.68	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 0	---	---	---
Percentage Glycol	%	■ 50.3	---	---	---
Freezing Point	°C	■ -35	---	---	---



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC
 9601 BOGGY CREEK RD
 ORLANDO, FL
 US 32824
 Contact: Robert LaPlante
 robert.laplante@altg.com
 T: (407)508-9736
 F: (407)659-8720

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: VOLVO0096
Unique No: 10617801
Signed: Doug Bogart
Report Date: 26 Aug 2023




CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver



Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

