CONSTRUCTION EQUIPMENT G07590 VOLVO A40D 70043 - COOLANT



 Sample No:
 VCP435249

 Oil Type:
 NOT GIVEN

 Job No:
 G07590

VOLVO

SAMPLE II	NFORMATION			
Sample Number	-	VCP435249	 	
Sample Date		18 Jul 2023	 	
Machine Hours		14731	 	
Sample Status		NORMAL	 	
VOLVO	CONDITION			
	CONDITION			
рН	Scale 0-14	8.08	 	
Reserve Alkalinity	Scale 0-20		 	
Nitrites	ppm	NT NT	 	
Percentage Glycol	%	49.8	 	
Freezing Point	°C	-33	 	
VOLVO				
CONTAMI	VATION		 	
Coolant Appearance		normal	 	
Coolant Color		Red	 	



BLENHEIM CONSTRUCTION

302 INDEPENDENCE BLVD SICKLERVILLE, NJ US 08081 Contact: KEN LARDI klardi@blenheimconstruction.com T: (856)728-8880 F: (856)728-8866

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot:BLECAMUnique No:10618321Signed:Jonathan HesterReport Date:28 Aug 2023

CONSTRUCTION EQUIPMENT



GRAPHS

Iron/Tin/Silver

VOLVO

