

CONSTRUCTION EQUIPMENT VOLVO L60H 621848 - DIESEL ENGINE



Sample No: VCP426586

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

Job No:

VOLVO				
SAMPLE II	NFORMATION			
Sample Number		VCP426586	VCP254569	
Sample Date		18 Aug 2023	04 Oct 2019	
Machine Hours		4546	494	
Oil Hours		0	0	
Oil Changed		Changed	Changed	
Sample Status		ABNORMAL	ABNORMAL	
OIL CONDI	TION			
Visc @ 100°C	cSt	14.0	12.3	
Base Number (BN)		■ 5.4		
Oxidation (PA)	%	90	71	
CONTAMIN	NATION			
		_		
Soot %	%	2	0.2	
Nitration (PA)	%	119	55	
Sulfation (PA)	%	83	56	
Glycol	%	NEG	NEG	
Fuel Silicon	%	<1.0 14	<1.0	
Sodium	ppm	5	5	
Potassium	ppm	4	0	
1 Otassium	ррш			
VOLVO	TALE			
WEAR ME	IAL3			
Iron	ppm	<u> </u>	4 5	
Copper	ppm	■ 13	■8	
Lead	ppm	2	■3	
Tin	ppm	4	0	
Aluminum	ppm	<u>^</u> 68	▲ 71	
Chromium	ppm	8	10	
Molybdenum	ppm	60	3 4	
Nickel Titanium	ppm	□ <1 0	<1	
Silver	ppm	0	0	
Manganese	ppm	2	5	
Vanadium	ppm	<1	0	
Variaciani	ррш	~1	O	
ADDITIVE	7			
Calcium	ppm	1795	□ 1486	
Magnesium	ppm	632	570	
Zinc	ppm	1277	875	
Phosphorus	ppm	966	804	
Barium	ppm	■0	□ <1	
Boron	ppm	<u> </u>	4 0	
	1-1			



ALTA EQUIPMENT COMPANY

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905 Contact: TODD LARK tlark@altaequipfl.com

T:

F: (239)481-3302

Diagnosis

Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition. Piston, ring and cylinder wear is indicated. All other component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0090Unique No:10619890Signed:Don BaldridgeReport Date:28 Aug 2023



CONSTRUCTION EQUIPMENT





