



CONSTRUCTION EQUIPMENT

593983 RYAN GOLF VOLVO A45G 342685 - FRONT AXLE



Sample No: VCP416403
Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5
Job No: 593983 RYAN GOLF



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: JOHN FARDELLA
JFARDELLA@ALTAEQUIPFL.COM
T: (813)630-0077
F: (813)630-2233



SAMPLE INFORMATION

Sample Number	VCP416403	---	---	---
Sample Date	11 Aug 2023	---	---	---
Machine Hours	4733	---	---	---
Oil Hours	4733	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	█ 301	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 8	---	---	---
Sodium	ppm	█ 2	---	---	---
Potassium	ppm	█ <1	---	---	---



WEAR METALS

Iron	ppm	█ 236	---	---	---
Copper	ppm	█ <1	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 2	---	---	---
Molybdenum	ppm	█ 9	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	█ 0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 6	---	---	---
Vanadium	ppm	█ <1	---	---	---



ADDITIVES

Calcium	ppm	█ 89	---	---	---
Magnesium	ppm	█ 19	---	---	---
Zinc	ppm	█ 49	---	---	---
Phosphorus	ppm	█ 1012	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 190	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0093
Unique No: 10620311
Signed: Wes Davis
Report Date: 25 Aug 2023



CONSTRUCTION EQUIPMENT



GRAPHS

