

CONSTRUCTION EQUIPMENT
SWA292727 SENNEBOGEN 860 860.0.1095 - REAR RIGHT FINAL

Sample No: VCP410320

Oil Type: **GEAR OIL SAE 80W90** 

Job No: SWA292727

CVMDIE	INFORMATION				
	INFURMATION				
Sample Number		VCP410320			
Sample Date		25 Aug 2023			
Machine Hours		10929			
Oil Hours		0			
Oil Changed		Not Changd			
Sample Status		NORMAL			
VOLVO					
OIL CONDITION					
Visc @ 40°C	cSt	<b>177</b>			
V13C @ 40 C	CSt				
VOLVO					
CONTAM	INATION				
Silicon	ppm	<b>7</b>			
Sodium	ppm	■5			
Potassium	ppm	<b>■&lt;1</b>			
WEAR METALS					
	-			-	
Iron	ppm	<b>■</b> 179			
Copper	ppm	<b>45</b>			
Lead	ppm	0			
Tin	ppm	<b>2</b>			
Aluminum	ppm	■4			
Chromium	ppm	<b>1</b>			
Molybdenum	ppm	■0			
Nickel	ppm	<b>■</b> <1			
Titanium	ppm	2			
Silver	ppm	0			
Manganese	ppm	■3			
Vanadium	ppm	0			
VOLVO					
<b>ADDITIV</b>	23				
Calcium	ppm	<b>1</b> 4			
Magnesium	ppm	<b>4</b>			
Zinc	ppm	<b>■</b> 22			
Phosphorus	ppm	<b>1290</b>			
Barium	ppm	<b>295</b>			
Boron	ppm	<b>24</b>			



**ALTA EQUIPMENT CO - ORLAND PARK** 5000 INDUSTRIAL HWY GARY, IN US 46406 Contact: DAVE ENG DAVE.ENG@ALTG.COM T: (312)350-2560 F:

## Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO8885 **Unique No:** 10622871 Signed: Don Baldridge Report Date: 30 Aug 2023



## **CONSTRUCTION EQUIPMENT**





## **GRAPHS**

