

## **CONSTRUCTION EQUIPMENT**

4241 VOLVO EC480E 315141 - LEFT SWING DRIVE

Sample No: VCP412212

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

**Job No:** SPM594241

VOLVO					
SAMPLE INFORMATION					
Sample Number	-	VCP412212			
Sample Date		16 Aug 2023			
Machine Hours		1133			
Oil Hours		0			
Oil Changed		Changed			
Sample Status		NORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	<b>173</b>			
CONTAMINATION					
Silicon	ppm	<b>□32</b>			
Sodium	ppm	<b>■</b> <1			
Potassium	ppm	<b>■</b> <1			
Totassidiii	ррш				
VOLVO					
WEAR M	ETALS				
Iron	ppm	<b>146</b>			
Copper	ppm	<b>22</b>			
Lead	ppm	■0			
Tin	ppm	<b>■</b> <1			
Aluminum	ppm	■3			
Chromium	ppm	■3			
Molybdenum	ppm	■0			
Nickel	ppm	<b>■</b> 0			
Titanium	ppm	0			
Silver	ppm	0			
Manganese	ppm	■4			
Vanadium	ppm	0			
ADDITIV	ES				
Calcium	ppm	■8			
Magnesium	ppm	<b>■&lt;1</b>			
Zinc	ppm	<b>16</b>			
Phosphorus	ppm	■ 342			
Barium	ppm	<b>■</b> 2			
Boron	ppm	<b>■</b> 0			



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0093Unique No:10629970Signed:Angela BorellaReport Date:31 Aug 2023



## **CONSTRUCTION EQUIPMENT**





## GRAPHS

