

CONSTRUCTION EQUIPMENT 10998 VOLVO A30D 12131 - DIESEL ENGINE



Sample No: VCP412357

Oil Type: DIESEL ENGINE OIL SAE 15W40

Job No: 10998

Potassium

ppm

VOLVO							
SAMPLE II	NFORMATION						
Sample Number	-	VCP412357	VCP378626	VCP348522	VCP285557		
Sample Date		27 Aug 2023	08 Aug 2022	28 Jan 2022	22 Sep 2020		
Machine Hours		11023	10705	10505	10330		
Oil Hours		0	250	250	250		
Oil Changed		Changed	Changed	Changed	Changed		
Sample Status		NORMAL	NORMAL	NORMAL	NORMAL		
OIL CONDITION							
Visc @ 100°C	cSt	11.9	12.2	12.4	12.6		
Base Number (BN)	mg KOH/g	■9.1	11.1	■10.9			
Oxidation (PA)	%	62	78	81	76		
CONTAMINATION							
Soot %	%	□0.5	□0.2	□ 0.2	□0.1		
Nitration (PA)	%	58	54	56	48		
Sulfation (PA)	%	55	62	64	61		
Glycol	%	NEG	NEG	NEG	NEG		
Fuel	%	■2.8	< 1.0	<1.0	<1.0		
Silicon	ppm	■5	4	□4	5		
Sodium	ppm	■<1	2		2		

VOLVO						
WEAR METALS						
Iron	ppm	■8	<u></u> 5	4	3	
Copper	ppm	■ <1	<1	- <1		
Lead	ppm	■ <1	< 1	0	0	
Tin	ppm	■0	- <1	□ 0	□0	
Aluminum	ppm	1	< 1	- <1	1	
Chromium	ppm	■<1	- <1	- <1	□0	
Molybdenum	ppm	■30	45	■36	■ 36	
Nickel	ppm	■<1	< 1	□ 0	□0	
Titanium	ppm	■ <1	1	0	<1	
Silver	ppm	■ 0	<1	0	0	
Manganese	ppm	■<1	< 1	- <1	- <1	
Vanadium	ppm	0	<1	0	0	

ADDITIVES						
Calcium	ppm	1767	■1571	■1688	1647	
Magnesium	ppm	■331	483	■ 528	□532	
Zinc	ppm	1032	□1023	■998	■994	
Phosphorus	ppm	■860	■838	■894	■882	
Barium	ppm	□ 0	< 1	■0	0	
Boron	ppm	■37	■81	□ 66	6 1	



JAMES J ANDERSON

6958 TORRESDALE AVENUE
PHILADELPHIA, PA
US 19135
Contact: JOHN HERBUT
herb@jjaconstruction.com
T: (215)850-9051
F: (215)427-0208

Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. No other corrective action is recommended at this time.All component wear rates are normal. Light fuel dilution occurring. No other contaminants were detected in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:JAAPHIUnique No:10630063Signed:Wes DavisReport Date:01 Sep 2023



CONSTRUCTION EQUIPMENT





