



# CONSTRUCTION EQUIPMENT

W02007468 VOLVO A45G 352364 - TRANSMISSION



**Sample No:** VCP418752  
**Oil Type:** MOBIL AT 102  
**Job No:** W02007468



## SAMPLE INFORMATION

Sample Number	VCP418752	---	---	---
Sample Date	28 Aug 2023	---	---	---
Machine Hours	4016	---	---	---
Oil Hours	2000	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

**MCCLUNG-LOGAN EQUIPMENT CO INC**  
8450 QUARRY ROAD  
MANASSAS, VA  
US 20110  
Contact: MIKE MAYHUGH  
MMAYHUGH@MCCLUNG-LOGAN.COM  
T: (703)393-7344  
F: (703)393-7844



## OIL CONDITION

Visc @ 40°C	cSt	█ 26.1	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	█ 13	---	---	---
Sodium	ppm	█ 9	---	---	---
Potassium	ppm	█ 4	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



## WEAR METALS

Iron	ppm	█ 93	---	---	---
Copper	ppm	█ 160	---	---	---
Lead	ppm	█ 2	---	---	---
Tin	ppm	█ 18	---	---	---
Aluminum	ppm	█ 35	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	<1	---	---	---
Nickel	ppm	█ 28	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	6	---	---	---
Vanadium	ppm	<1	---	---	---



## ADDITIVES

Calcium	ppm	107	---	---	---
Magnesium	ppm	4	---	---	---
Zinc	ppm	12	---	---	---
Phosphorus	ppm	188	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	71	---	---	---

**Depot:** VOLVO0002  
**Unique No:** 10631664  
**Signed:** Don Baldrige  
**Report Date:** 06 Sep 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

