

## CONSTRUCTION EQUIPMENT SPM581116 VOLVO L150H 7135 - DIESEL ENGINE



Sample No: VCP422997

Oil Type: DIESEL ENGINE OIL SAE 15W40

**Job No:** SPM581116

TIOTIVO				
SAMPLE INFORMATION				
Sample Number	VCP422997	VCP420066	VCP387159	
Sample Date	25 Aug 2023	24 Apr 2023	22 Feb 2023	
Machine Hours	4044	562	276	
Oil Hours	0	0	0	
Oil Changed	Changed	Changed	Not Changd	
Sample Status	NORMAL	ABNORMAL	ATTENTION	

OIL CONDITION								
Visc @ 100°C	cSt	<b>13.6</b>	<b>▲</b> 11.2	<b>▲</b> 11.1				
Base Number (BN)	mg KOH/g	■9.8	■5.0	■10.0				
Oxidation (PA)	%	56	61	53				

CONTAMINATION						
Soot %	%	■0.1	□0.1	■ 0.1		
Nitration (PA)	%	53	73	48		
Sulfation (PA)	%	51	52	50		
Glycol	%	NEG	NEG	NEG		
Fuel	%	<1.0	< 1.0	■ 0.5		
Silicon	ppm	<b>■</b> 3	<b>2</b> 1	<b>2</b>		
Sodium	ppm	<b>2</b>	<b>2</b>	<b>0</b>		
Potassium	ppm	<b>■&lt;1</b>	<b>3</b>	<b>1</b>		

WEAR N	METALS				
Iron	ppm	■3	8	<b>7</b>	
Copper	ppm	<b>■</b> 2	<u>^</u> 221	<b>2</b> 9	
Lead	ppm	<b>■</b> 0	< 1	< 1	
Tin	ppm	<b>■&lt;1</b>	2	<b>-</b> <1	
Aluminum	ppm	<b>■&lt;1</b>	<b>2</b>	<b>2</b>	
Chromium	ppm	<b>■&lt;1</b>	0	□0	
Molybdenum	ppm	<b>63</b>	<b>1</b> 76	<b>47</b>	
Nickel	ppm	■0	0	<b>0</b>	
Titanium	ppm	<b>□</b> 0	<b>0</b>	<b>-</b> <1	
Silver	ppm	<b>■</b> 0	0	<b>0</b>	
Manganese	ppm	<b>■&lt;1</b>	<b>■</b> 3	< 1	
Vanadium	ppm	0	0	0	

ADJITIODA					
Calcium	ppm	<b>1107</b>	<b>1</b> 968	■1348	
Magnesium	ppm	<b>1047</b>	<b>4</b> 0	■ 588	
Zinc	ppm	<b>1366</b>	<b>1166</b>	<b>1065</b>	
Phosphorus	ppm	<b>1105</b>	909	■935	
Barium	ppm	<b>0</b>	<b>0</b>	<b>0</b>	
Boron	ppm	<b>3</b>	<b>4</b> 5	<b>2</b> 3	



## **WASTE MANAGEMENT - GARY**

1508 SHERMAN ST
GARY, IN
US 46406

Contact: TARA RORK

T: F:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:WASGARINUnique No:10632409Signed:Wes DavisReport Date:05 Sep 2023



## **CONSTRUCTION EQUIPMENT**





