

# CONSTRUCTION EQUIPMENT SPM593813 VOLVO L90E 28002 - DIESEL ENGINE



Sample No: VCP415245

Oil Type: DIESEL ENGINE OIL SAE 15W40

**Job No:** SPM593813

SAMPLE INFORMATI	ON		
Sample Number	VCP415245	VCP377918	 
Sample Date	25 Aug 2023	24 May 2022	 
Machine Hours	22201	20455	 
Oil Hours	0	0	 
Oil Changed	Changed	Changed	 
Sample Status	NORMAL	NORMAL	 

OIL CONDIT	<b>FION</b>			
Visc @ 100°C	cSt	<b>14.4</b>	<b>14.1</b>	 
Base Number (BN)	mg KOH/g	■8.6	■9.1	 
Oxidation (PA)	%	73	88	 

CONTAI	MINATION			
Soot %	%	■0.4	□ 0.4	 
Nitration (PA)	%	81	73	 
Sulfation (PA)	%	59	64	 
Glycol	%	NEG	NEG	 
Fuel	%	<1.0	< 1.0	 
Silicon	ppm	<b>■</b> 4	<b>4</b>	 
Sodium	ppm	<b>2</b>	<b>-</b> <1	 
Potassium	ppm	<b>■&lt;1</b>	<b>2</b>	 

Iron         ppm         10         8            Copper         ppm         2         <1            Lead         ppm         1         <1            Tin         ppm         <1         <1            Aluminum         ppm         1         2            Chromium         ppm         <1         <1	
Lead         ppm         1         <1	
Tin         ppm            Aluminum         ppm         1         2	
Aluminum ppm <b>1</b> 2	
<b>Chromium</b> ppm <b>□ &lt;1</b>	
<b>Molybdenum</b> ppm <b>■59</b> ■38	
Nickel ppm <b>□0</b>	
<b>Titanium</b> ppm <b>■0</b>	
Silver	
Manganese ppm <b>■ &lt;1</b>	
Vanadium ppm <b>0</b>	

ADDIT	Zav			
Calcium	ppm	<b>1127</b>	■1738	 
Magnesium	ppm	■ 995	<b>459</b>	 
Zinc	ppm	<b>1337</b>	■968	 
Phosphorus	ppm	<b>1029</b>	<b>775</b>	 
Barium	ppm	<b>0</b>	□ 0	 
Boron	ppm	<b>2</b>	□ 50	 



### **VICTORY AUTO WRECKERS**

710 EAST GREEN STREET BENSENVILLE, IL US 60196

Contact: SERVICE MANAGER

T: (630)860-2000 F:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VICBENUnique No:10632427Signed:Wes DavisReport Date:05 Sep 2023



# **CONSTRUCTION EQUIPMENT**





#### GRAPHS

