

CONSTRUCTION EQUIPMENT

1594509 VOLVO L120H 633267 - HYDRAULIC SYSTEM

Sample No: VCP415437

Oil Type: AW HYDRAULIC OIL ISO 46

Job No: SPM594509

SAMPLE INFORMATION			
Sample Number	VCP415437	 	
Sample Date	17 Aug 2023	 	
Machine Hours	1035	 	
Oil Hours	0	 	
Oil Changed	Not Changd	 	
Sample Status	ATTENTION	 	

OIL CONDI	TION			
Visc @ 40°C	cSt	42.8	 	
Acid Number (AN)	mg KOH/g	■ 0.34	 	

CONT	TAMINATION			
Particles >4µn	n	<u> </u>	 	
Particles > 6µm	n	■875	 	
Particles >14µ	m	28	 	
ISO 4406:1999) (c)	20/17/12	 	
Silicon	ppm	■3	 	
Sodium	ppm	■0	 	
Potassium	ppm	■<1	 	

WEAR	METALS			
Iron	ppm	■3	 	
Copper	ppm	1	 	
Lead	ppm	■ <1	 	
Tin	ppm	■ 0	 	
Aluminum	ppm	0	 	
Chromium	ppm	■ <1	 	
Molybdenum	ppm	■ <1	 	
Nickel	ppm	■ 0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	

ADDITI	VES			
Calcium	ppm	66	 	
Magnesium	ppm	■ 4	 	
Zinc	ppm	433	 	
Phosphorus	ppm	■326	 	
Barium	ppm	2	 	
Boron	ppm	■ 0	 	



OZINGA BROS INC

19001 OLD LAGRANDE RD
MOKENA, IL
US 60448
Contact: ED JONGSMA

T: (708)326-4200 F:

Diagnosis

We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. There is a light amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Depot:OZIMOKVCUnique No:10632695Signed:Wes DavisReport Date:06 Sep 2023



CONSTRUCTION EQUIPMENT





GRAPHS

