CONSTRUCTION EQUIPMENT SPM594086 CATERPILLAR 815F 1GN008886 - HYDRAULICSYSTI

Sample No:VCP420659Oil Type:VOLVO SUPER HYDRAULIC OIL 46Job No:SPM594086

SAMPLE INFORMATION

VOLVO

Sample Number	-	VCP420659	 	
Sample Date		25 Aug 2023	 	
Machine Hours		5625	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
OIL CONDI	TION			
Visc @ 40°C	cSt	40.5	 	
Acid Number (AN)	mg KOH/g	1.05	 	
VOLVO				

CONTAN	MINATION			
Particles >4µm		17240	 	
Particles >6µm		<u> </u>	 	
Particles >14µm		57	 	
ISO 4406:1999 (c)	21/19/13	 	
Silicon	ppm	5	 	
Sodium	ppm	0	 	
Potassium	ppm		 	

Iron	ppm	3	 	
Copper	ppm	51	 	
Lead	ppm	 <1	 	
Tin	ppm	0	 	
Aluminum	ppm	 <1	 	
Chromium	ppm	 <1	 	
Molybdenum	ppm	 <1	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	

	IVE2			
Calcium	ppm	401	 	
Magnesium	ppm	134	 	
Zinc	ppm	989	 	
Phosphorus	ppm	801	 	
Barium	ppm	2	 	
Boron	ppm	5	 	



JOHN KENO & CO

750 RICARD LN ELK GROVE VILLAGE, IL US 60007 Contact: LUKAS DECKER Idecker@johnkeno.com T: (847)340-2432 F:

Diagnosis

The filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.All component wear rates are normal. There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

 Depot:
 JOHELK

 Unique No:
 10632703

 Signed:
 Wes Davis

 Report Date:
 06 Sep 2023

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO

