



CONSTRUCTION EQUIPMENT

SPM581116 VOLVO L150H 7135 - FRONT AXLE



Sample No: VCP422965
Oil Type: VOLVO WET BRAKE TRANSAXLE OIL
Job No: SPM581116



SAMPLE INFORMATION

Sample Number	VCP422965	VCP420660	VCP422836	VCP420063
Sample Date	25 Aug 2023	25 Aug 2023	12 Jun 2023	24 Apr 2023
Machine Hours	4044	995	774	562
Oil Hours	0	0	0	0
Oil Changed	Changed	Changed	Not Changd	Not Changd
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

WASTE MANAGEMENT - GARY
 1508 SHERMAN ST
 GARY, IN
 US 46406
 Contact: TARA RORK



OIL CONDITION

Visc @ 40°C	cSt	39.8	39.8	40.7	40.6
-------------	-----	-------------	------	------	------

T:
F:



CONTAMINATION

Silicon	ppm	11	13	10	12
Sodium	ppm	<1	<1	11	11
Potassium	ppm	2	2	<1	<1

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	39	46	47	42
Copper	ppm	3	2	<1	0
Lead	ppm	0	0	0	0
Tin	ppm	0	0	<1	0
Aluminum	ppm	1	1	<1	1
Chromium	ppm	<1	<1	2	2
Molybdenum	ppm	<1	<1	5	5
Nickel	ppm	0	0	0	0
Titanium	ppm	0	0	<1	0
Silver	ppm	0	0	0	0
Manganese	ppm	2	1	4	4
Vanadium	ppm	0	0	0	0



ADDITIVES

Calcium	ppm	3226	3521	3591	4002
Magnesium	ppm	7	8	14	12
Zinc	ppm	1488	1596	1497	1623
Phosphorus	ppm	1272	1347	1220	1337
Barium	ppm	2	2	0	0
Boron	ppm	58	57	154	137

Depot: WASGARIN
Unique No: 10633242
Signed: Wes Davis
Report Date: 06 Sep 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

