



# CONSTRUCTION EQUIPMENT

346709 VOLVO A30G 753194 - DROP BOX



**Sample No:** VCP432656

**Oil Type:** NOT GIVEN

**Job No:** 346709



## SAMPLE INFORMATION

Sample Number	VCP432656	---	---	---
Sample Date	29 Aug 2023	---	---	---
Machine Hours	1140	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

**ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC**  
 9601 BOGGY CREEK RD  
 ORLANDO, FL  
 US 32824  
 Contact: STAN ANDERSON  
 stan.anderson@altg.com  
 T:  
 F: (407)659-8720



## OIL CONDITION

Visc @ 40°C	cSt	█47.4	---	---	---
-------------	-----	-------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	█24	---	---	---
Sodium	ppm	█2	---	---	---
Potassium	ppm	█2	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



## WEAR METALS

Iron	ppm	█58	---	---	---
Copper	ppm	█2	---	---	---
Lead	ppm	█0	---	---	---
Tin	ppm	█0	---	---	---
Aluminum	ppm	█7	---	---	---
Chromium	ppm	█<1	---	---	---
Molybdenum	ppm	4	---	---	---
Nickel	ppm	█0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	2	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	47	---	---	---
Magnesium	ppm	4	---	---	---
Zinc	ppm	53	---	---	---
Phosphorus	ppm	2370	---	---	---
Barium	ppm	2	---	---	---
Boron	ppm	211	---	---	---

**Depot:** VOLVO0096  
**Unique No:** 10633278  
**Signed:** Don Baldrige  
**Report Date:** 07 Sep 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

