



# CONSTRUCTION EQUIPMENT

## VOLVO A30F 342009 - TRANSMISSION (AUTO)



**Sample No:** VCP382660  
**Oil Type:** DEXRON III  
**Job No:**



### SAMPLE INFORMATION

Sample Number	VCP382660	---	---	---
Sample Date	22 Aug 2023	---	---	---
Machine Hours	6348	---	---	---
Oil Hours	5	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

**GLOVER CONSTRUCTION CO. INC.**  
 4493 US HWY 301 N  
 PLEASANT HILL, NC  
 US 27866  
 Contact: BRENDA GAY  
 bgay@gloverconstruction.com  
 T:  
 F: (252)536-5078



### OIL CONDITION

Visc @ 40°C	cSt	■ 30.6	---	---	---
-------------	-----	--------	-----	-----	-----



### CONTAMINATION

Silicon	ppm	■ 3	---	---	---
Sodium	ppm	■ 0	---	---	---
Potassium	ppm	■ <1	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



### WEAR METALS

Iron	ppm	■ 5	---	---	---
Copper	ppm	■ 4	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ <1	---	---	---
Aluminum	ppm	■ 1	---	---	---
Chromium	ppm	■ 0	---	---	---
Molybdenum	ppm	■ <1	---	---	---
Nickel	ppm	■ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	■ 0	---	---	---
Manganese	ppm	■ 0	---	---	---
Vanadium	ppm	0	---	---	---



### ADDITIVES

Calcium	ppm	■ 130	---	---	---
Magnesium	ppm	■ 9	---	---	---
Zinc	ppm	■ 19	---	---	---
Phosphorus	ppm	■ 277	---	---	---
Barium	ppm	■ 2	---	---	---
Boron	ppm	■ 142	---	---	---

**Depot:** GLOPLE  
**Unique No:** 10633294  
**Signed:** Don Baldrige  
**Report Date:** 07 Sep 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

