



CONSTRUCTION EQUIPMENT

SWO065411 SUNBELT DOOSAN C-185 496404UIAD087 - DIESEL FUEL



Sample No: VCP388214
Oil Type: NOT GIVEN
Job No: SWO065411 SUNBELT



SAMPLE INFORMATION

Sample Number	VCP388214	---	---	---
Sample Date	30 Aug 2023	---	---	---
Machine Hours	1469	---	---	---
Sample Status	NORMAL	---	---	---

COWIN EQUIPMENT - ATLANTA

5710 RIVERVIEW RD
MABLETON, GA
US 30126

Contact: MIKE ANDREWS
mandrews@cowin.com

T: (404)690-7210

F:



FUEL CONDITION

Sulfur	ppm	0	---	---	---
Visc @ 40°C	cSt	2.46	---	---	---



CONTAMINATION

Water	%	0.004	---	---	---
Lead	ppm	0	---	---	---
Nickel	ppm	0	---	---	---
Aluminum	ppm	<1	---	---	---
Vanadium	ppm	<1	---	---	---
Silicon	ppm	0	---	---	---

Diagnosis

No corrective action is recommended at this time. All metal levels are normal indicating no corrosion in the system. There is no indication of any contamination in the fuel. The condition of the fuel is acceptable for the time in service.

Depot: COWMAB

Unique No: 10633361

Signed: Doug Bogart

Report Date: 21 Sep 2023



CONSTRUCTION EQUIPMENT



GRAPHS

Pensky-Martens Flash Point (°C)

