CONSTRUCTION EQUIPMENT SWA341088 VOLVO L150G 22536 - COOLANT



 Sample No:
 VCP432740

 Oil Type:
 VOLVO COOLANT VCS (YELLOW)

 Job No:
 SWA341088

VOLVO

	NFORMATION			
	AF URMATION	<u>.</u>		_
Sample Number		VCP432740	 	
Sample Date		26 Aug 2023	 	
Machine Hours		16482	 	
Sample Status		NORMAL	 	
VOLVO				
	CONDITION			
рН	Scale 0-14	7.68	 	
Reserve Alkalinity	Scale 0-20		 	
Nitrites	ppm	0	 	
Percentage Glycol	%	69.7	 	
Freezing Point	°C	-66	 	
VOLVO				
CONTAMI	VATION			
Coolant Appearance		normal	 	
Coolant Color		Orange	 	



MR BULTS INC

SULLIVAN COUNTY LANDFILL MONTICELLO, NY US 12701 Contact:

T: (208)324-7148 F:

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. The glycol level is high. Carboxylate test failed. The pH level of this fluid is within the acceptable limits.

Depot:MRBMONNYUnique No:10633423Signed:Doug BogartReport Date:08 Sep 2023

Contact/Location: ? ? - MRBMONNY

CONSTRUCTION EQUIPMENT



GRAPHS

Iron/Tin/Silver

VOLVO

